

DATED: September 6, 1990 CLIENT: David Huelstar OWNER OF RECORD:

THERE ARE NO IMPROVEMENTS ON THE PARCEL.

W. Vanni P.O. BOX 1632

BOX 1632 MARTINSVILLE, INDIANA 46151 17. 医内侧足部骨

SURVE PHONE (317) 342-3720 DRAPALIK SURVEYING AND ENGINEERING 19 WEST WASHINGTON STREET MARTINSVILLE, INDIANA 46151 PHONE: 317-342-3806

SURVEY FOR MICHAEL W. ETIENNE

Owner of Record

Lot Number 990 - Foxcliff South Associates, Inc.

Lot Number 991 - Michael W. and Susan L. Etienne

Lot Number 992 - Foxcliff South Associates, Inc.

DESCRIPTION: A part of Lot Number 990 in Foxcliff Estates South, Section XXXVIII, as per plat thereof recorded in Deed Record 299, page 267 in the Office of the Recorder of Morgan County, Indiana, being more particularly described as follows:

Beginning at an iron pin (capped S 0034) marking the northeast corner of said Lot Number 990, thence traverse along the east line of said Lot Number 990, South 25 degrees 36 minutes 11 seconds West, 180.40 feet (South 26 degrees 00 minutes 00 seconds West, 180.00 feet as per plat) to an iron pin (found) marking the southeast corner of said Lot Number 990; thence traverse along the south line of said Lot Number 990, North 52 degrees 45 minutes 12 seconds West, 18.45 feet; thence traverse North 29 degrees 40 minutes 22 seconds East, 108.77 feet to a corner of a concrete driveway; thence traverse North 29 degrees 40 minutes 22 seconds East, 68.40 feet to an iron pin (found) on the north line of said Lot Number 990; thence traverse along the said north line, South 63 degrees 48 minutes 09 seconds East (South 64 degrees 00 minutes 00 seconds East as per plat), 5.50 feet to the Point of Beginning. Containing 0.05 of an acre, more or less.

DESCRIPTION: A part of Lot Number 991 in Foxcliff Estates South, Section XXXVIII, as per plat thereof recorded in Deed Record 299, page 267 in the Office of the Recorder of Morgan County, Indiana, being more particularly described as follows:

Beginning at an iron pin (capped S 0034) marking the northeast corner of said Lot Number 991, thence traverse along the east line of said Lot Number 991, South 25 degrees 35 minutes 53 seconds West (South 26 degrees 00 minutes 00 seconds West as per plat), 180.00 feet to an iron pin (found) marking the southeast corner of said Lot Number 991; thence traverse along the south line of said Lot Number 991, North 64 degrees 00 minutes 00 seconds West, 18.32 feet to an iron pin (capped S 0034); thence traverse North 29 degrees 40 minutes 23 seconds East, 180.38 feet to an iron pin (capped S 0034) on the north line of said Lot Number 991; thence traverse along said north line, South 63 degrees 48 minutes 10 seconds East (South 64 degrees 00 minutes 00 seconds East as per plat), 5.50 feet to the Point of Beginning. Containing 0.05 of an acre, more or less.

SURVEYOR'S REPORT:

This survey has been prepared in order to create a parcel to eliminate the encroachment of a concrete driveway onto Lot Number 990. A portion of Lot Number 990 is to be exchanged for a portion of equal area of Lot Number 991. Lot Numbers 990 and 992 are currently owned by the same individual. The monuments being shown as found on the attached drawing were used as a basis for this survey.

A distance-distance intersection was computed (between the iron pin found at the P.C. on the north line of Lot Number 990 and the iron pin found marking the southeast corner of Lot Number 991) in order to determine the location of the northeast corner of Lot Number 991.

Although the distance between this stone and the southeast corner of Lot Number 991 was measured to be 0.06 of a foot from the platted distance, the bearing of this line varied by 01 degree 01 minute 37 seconds of the value computed from the plat. This equates to a theorhetical uncertainty of approximately six (6) feet for the corners found and/or set as part of this survey.

There are improvements on Lot Number 991 in said Foxcliff Estates South, Section XXXVIII. There are no improvements on Lot Number 990.

FLOOD CERTIFICATION: I certify that this property is not in a special flood hazard zone as shown on the U.S. Department of Housing and Urban Developement Map Number 180176 0100 B.

In accordance with Title 864 Article 1.1 Chapter 13, Section 1 through 34 of the Indiana Administrative Code, the following locations of the lines and corners established on this survey as a result of:

A) Discrepancies in record descriptions and plats

Approximately 6.0 feet in the difference of the computed and measured position of the southeast corner of Lot Number 991 (bearings as stated above).

B) Random Errors in Measurements (Theoretical Uncertainty)

Due to the Theoretical Uncertainty (due to random errors in measurement) of the corner of the subject tract established by this survey is within the specifications for a Class B Survey (0.25 feet) as defined in IAC 864.

CERTIFICATION: I hereby certify that I have surveyed the above described property and that the attached drawing represents the survey.

John E. Drapalik

Reg. Land Surveyor, S 0034

State of Indiana

July 1, 1992

BOOK 3 PAGE 248

RECEIVED FOR RECORD

'92 OCT 30 PM 3 41

Carocolla Hacker MORGAN COUNTY RECORDER SUNDERLAND DRIVE (so. Ruy 990 5.50 DRIVE v/, NSZ. AS TELL SW COR LOT 991 SE COR LOT 991