Morgan County Surveyor's Office

Terry Brock, Surveyor Bill Dials, Stormwater Coordinator

180 South Main Street, Suite 010 Martinsville, IN 46151 Morgancountysurveyor.com



Phone: 765-342-1064 Fax: 765-342-1063

E-mail: tbrock@morgancounty.in.gov bdials@morgancounty.in.gov

March 7, 2016

To: Morgan County Drainage Board

Re: Drain Classification

Under the authority of the Indiana Drainage code: IC 36-9-27-34, I hereby submit the following drains for classification:

DRAINS IN NEED OF RECONSTRUCTION:

NO DRAINS IN NEED OF RECONSTRUCTION

2. DRAINS IN NEED OF MAINTENANCE:

A. Hilldale Cemetery Drain

- 1. Spray both sides of the ditch, an approximate distance of 14,600 feet.
- 2. Small bank stabilization in a few areas.
- 3. 3 outlets were permitted to the City of Martinsville.

B. Lake Ditch

- 1. Spray both sides of the ditch, an approximate distance of 127,000 feet
- 2. Spray Bayless Ditch both sides, approximate distance of 18,800 feet.
- 3. Remove 2 beaver dams at Heremont Road.
- 4. Bank stabilization along Allan Ditch.

C. M. A. Nutter Drain

- 1. Spray both sides of the ditch, an approximate distance of 22,740 feet.
- 2. Tree removal is needed on South half of ditch.
- 3. 6 beavers and a dam were removed from the ditch.
- 4. Bank stabilized south of the railroad crossing
- 5. Trees were removed from railroad R/W South to the condominiums.

D. Lewis Sartor Drain

- 1. Spray both sides of the ditch, an approximate distance of 27,690 feet.
- 2. Stabilization of West bank along the parking lot of the Baptist Church on Columbus St.
- 3. 3 beavers and a dam were removed from the ditch at the field crossing by Indian Creek.
- 5. Lots of trash within the ditch, especially along the High School.
- 6. In talks with the City of Martinsville to replace old pipes under Columbus St.

3. DRAINS THAT SHOULD BE VACATED:

A. Michael Haase Ditch

I recommend the Board approve this Drain Classification List for 2016 as submitted.

Sincerely,

Terry Brock Surveyor, Morgan County